## FIELD INSPECTION REPORT

Date of I	nspection: /	9.12.2020	District: Malanda.	
Division	: Bihorrsh	ant.	Length (km): 0.350 KM.	
Name of	the Road: Be	hor-Nijay Ro	ad To Eakbalgand	
	Programme:	MAINTENANCE	MMGSY(GEN)	
Package	No.:		Road Id No.:	
Status of	the Project:		/Under Maintenance	
Work is	a case of:		Jp gradation/ Maintenance	
Sl. No.		Parameters to	be checked	Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing "			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)				Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			s/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furni	ture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			n Yes/No

Overall Rating

4.

a)

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Aject Kumar Sirll DESIGNATION: J-E

Compliance History

Status of ATR's & any others