

FIELD INSPECTION REPORT

Date of Inspection : 31-12-2020		District: RMB
Division : 95-1		Length (km): 1.4
Name of the Road: Salsagan dargah P.O. H. 2 - Dargah Shah / 4th / 6th / 10th / 12th / 14th / 16th / 18th / 20th / 22nd / 24th / 26th / 28th / 30th / 32nd / 34th / 36th / 38th / 40th / 42nd / 44th / 46th / 48th / 50th / 52nd / 54th / 56th / 58th / 60th / 62nd / 64th / 66th / 68th / 70th / 72nd / 74th / 76th / 78th / 80th / 82nd / 84th / 86th / 88th / 90th / 92nd / 94th / 96th / 98th / 100th		
Scheme/Programme: MAINTENANCE		
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railing/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	C
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

31/12/2020
(Signature)

NAME:

Umer

DESIGNATION:

BB