

FIELD INSPECTION REPORT

Date of Inspection : 24/12/2020	District: Ghorpuri
Division : 18-C	Length (km): 0.600
Name of the Road: Sargahua Porada Mahanir-tula Sargahua	
Scheme/Programme:	MAINTENANCE
Package No.: 1040/6130/2	Road Id No.: 1040/6130/2
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/L
b)	Condition of Abutment & Wing walls. Slab in RCC culverts	S/SRI/L
c)	Condition of railings/slab/approach for Bridges	S/SRI/L
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S.R.I.
Unsatisfactory (U)	

NAME:

Jedij
24/12/2020
(Signature) J.E.