FIELD INSPECTION REPORT

Date of Inspection :0%:	-01-21	District: Rolles
Division: Rw Dlu) division Sessi-1		Length (km): 2.20
	CARUP TO GUE	
Scheme/Programme:	MAINTENANCE	
Package No.: 117	asy	Road Id No.:
Status of the Project:	Ongoing/Completed	/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & mincuts if any	
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compositative Platory	
a)	Status of ATR's & any others	MO

Overall Rating

Satisfactory (S)	10'
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

11/000-01-2

(Signature)

NAME: Makest Probaded

DESIGNATION: J'E.