FIELD INSPECTION REPORT

trace of suppression : 0 % - 1 % /			District: Rolles	
Division: R. WD(W) dysyn, Laxon -1			Length (km): 0.525 19	
Name o	the Road: B	abrani Sendu	& PBUSS sad to Puter I	Jan zant
Sebeme	Programme:	MAINTENANCE		
		7.136SY	Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance		
Work is	a case of:		p gradation/ Maintenance	
SI. No.		Parameters to	se checked	Remarks
1.	Pavement			
a)	Road Junction condition			_ S/U
b)	Condition of Surfacing			- S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No.
g)	Compaction of flank/slope & raincuts if any			Yes/No
1	Cross Drains	9		1000
a)	Condition of h	ead walls in Hume pip	e culverts including its painting	S/SRI/U

Condition of Abutment & Wing walls, Slab in RCC culverts

stones/Pavement road markings are provided and maintained

Whether sign boards/informatory/cautionary Board/km & 200m

Condition of railings/slab/approach for Bridges

Overall Rating

b)

c)

8)

8)

Satisfactory (S)	187
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

S/SRI/U

S/SRI/U

Yes/No

the

(Signature)

NAME: Malest Prosectsol DESIGNATION: J.E

Road Furniture

Complaine History

Status of ATR's & any others