

FIELD INSPECTION REPORT

Date of Inspection : 30.12.2020		District : GAYA	
Division : Neemchak Bathani		Length (Km.) : 1.53 km	
Scheme/Programme : <u>Normal Rd. MAINTENANCE</u>		Road Id No. :	
Package No. : <u>GTSNY</u>		Ongoing/Completed/Under Maintenance	
Status of the Project :		New Connectivity/Up gradation/Maintenance	
Work is a case of :		Remarks	
Sl. No.	Parameters to be checked		
1	Pavement		
a)	Road Junction condition		✓ SU
b)	Condition of Surfacing		SU
c)	Riding Quality		SU
d)	Road Camber		✓ SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & rineuts if any		✓ Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	NA	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	NA	S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO	Yes/No
4	Compliance History		
a)	Status of ATR's & any others.	No ATR	✓

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires improvement (SRI)	SRI
Unsatisfactory (U)	—

30.12.2020
JE