FIELD INSPECTION REPORT

Date of Inspection: 23-12-2020		District: Awangabad	
Division: Dandragaz		Length (km):	
Name of the Road: -	Dihamilya Ba	Letter Rd. to Kestrari	
Scheme Programme:	MAINTENAN	CE : Lucia Rd. to Kestiari ;	
Package No.: BR-02 R- 004		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remark	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	·S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Shubban kon

DESIGNATION: J.E.