FIELD INSPECTION REPORT

ame of Road:		LO22 24 HOZARTI MAINTENANCE MMMSY (SC)	
		Onging/Completed/Under Maintenance New Connectivity/ Up Gradation/ Maintenance	
1	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any Yes/No		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting S/SF		S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U >
c)	Condition of railings/slabs//approach for Bridges S/SRI/I		S/SRI/U
3	Road Furniture		A Charles
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement Yes/No		Yes/No
4	Compliance History		
a)	Status of ATR & any others		HA
Overall	Grading:	Satisfactory (S)	-2-
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Ramoliande Rom.
Degisnation Junier Enserue

(Signature)