FIELD INSPECTION REPORT

Pate of Inspection: 28/12/20 District: 20 LEVZ			
Name of Road: SOTI MMUSY RIMIN - HAIMOR LE BD 3212 2			4 ann
Scheme/ Programme:		MAINTENANCE MM WSY (ST	
Package No. Road ID No.			
Status of the Project: Onging/Completed/Under Maintenance			
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber ~S/U		√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any Yes/No		
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting S/SRI/U		\S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slabs//approach for Bridges S/SRI/		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		1+17
Overall Grading:		Satisfactory (S)	-S -
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	Lancing and

Name: Ramchardserkonn Degisnation Junier Entiner

(Signature)