## FIELD INSPECTION REPORT

Date of Inspection :	30-12-2020	District:	Saran	chhapra
Division : SONE	PUR.	Length (km):	0.985	5
Name of the Road: N	Hig se Rasulpus	Panchayat Ohan	san hote H	Tak Pall moraya
Scheme/Programme:	MAINTENANCE			
Package No.:		Road Id No.:		
Status of the Project:	Ongoing/Completed	/Under Maintenan	ice	
Work is a case of:	New Connectivity/	Jp gradation/ Main	tenance	

SI. No.	Parameters to be checked	Remarks
1,	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
n	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
温泉"	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S) S.
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

(Signature)

NAME:

Rejendra Prasad.

DESIGNATION: A.G.