## FIELD INSPECTION REPORT

The Person Name of Street, or other Designation of the Person of the Per	pection :	30 12 20 20	District: SARAN (	CHHAPRA
	rision: SONE PUR. Length (km): 1.32			K-M -
ame of th		HAUSIA railue	line to chausia.	
	of smme:	MAINTENANCE		-1-5
			load Id No.:	
		THE RESERVE AND ADDRESS OF THE PARTY OF THE	/Under Maintenance	
Vork is a	case of:	New Connectivity/	Jp gradation/ Maintenance	
51. No.	Parameters to be checked			Remarks
1,	Pavement			
a)	Road Junction condition SAU			
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
0	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges S/SRI/U			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance History			
a)	Status of ATR's & any others			
	-		60.	S
Overall Rating :		Satisfactory (S)	requires Improvement (SRI)	
		Satisfactory but		

(Signature)

NAME: Rojanda Resed