

FIELD INSPECTION REPORT

Date of Inspection : 21.12.2020	District: Nalanda
Division : Bihar State	Length (km): 1.00 km
Name of the Road: Husainpur gaon ke Mahmadpur gaon Tak.	
Scheme/Programme: MAINTENANCE	4515
Package No.:	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

SL No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes.
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

A. Singh
21.12.20
(Signature)

NAME: Ajeet Kumar Singh

DESIGNATION: J.E