

ROAD INSPECTION REPORT

Date of Inspection: 30/12/2020		District: East Champaran -	
Location: Chakis		Length (Km):	
Name of the Road: Site Kund Brgm Astn to Chaitanpur Brgm.			
Stage No.:		Road ID No.:	
Type of the Project:		Ongoing/Completed/Under Maintenance	
It is a case of:		New Connectivity/Up Gradation/ Maintenance	
Parameters to be checked			
Pavement			Remarks
Road Junction condition			S
Condition of Surfacing			S
Riding Quality			S
Road Camber			
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
Contraction Joints provided or not (CC Pavement)			Yes/No
Compaction of Bank/slope & raincuts if any			SRI
Cross Drainage			
Condition of head walls in Hume pipe culverts including its painting			SRI
Condition of Abutment & Wing walls, Slab in RCC Culverts			S
Condition of railings/slab/approach for Bridges			
Road Furniture			
Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained			SRI
Compliance History:			
Status of ATR's & any others			
Overall Rating :		Satisfactory (S)	
		Satisfactory but requires improvement (SRI)	
		Unsatisfactory (U)	


 30/12/2020
 A.E.
 Chakis

(Signature)

AME :

DESIGNATION :