

FIELD INSPECTION REPORT

Date: 29-12-2020	District: East Champaran	
Location: Chakia	Length (Km): 1.275 K.M	
Road ID No.:		
Project:	Ongoing/Completed/Under Maintenance	
Work:	New Connectivity/Up Gradation/ Maintenance	
Parameters to be checked		Remarks
Condition		S
Junction condition		SRI
Condition of Surfacing		S
Quality		S
Camber		S
Free from defects such as visible cracks, exposed aggregates in CC Pavement.		yes/no
Expansion Joints provided or not (CC Pavement)		yes
Condition of Bank Slope & raincuts if any		
Drainage		
Condition of head walls in Hume pipe culverts including its painting		SRI
Condition of Abutment & Wing walls, Slab in RCC Culverts		
Condition of raftings/slab/approach for Bridges		
Furniture		
Warning sign board/Informatory/cautionary Board/Km & 200m		SRI
Pavement road markings are provided and maintained		
Accident History		
Number of ATR's & any others		
Overall Rating :	Satisfactory (S)	
	Satisfactory but requires improvement (SRI)	SRI
	Unsatisfactory (U)	


 29/12/2020
 A. E.
 Chakia

(Signature)

INATION :