FIELD INSPECTION REPORT

Date of Ir	spection:	1-12-2020 District: Derbhange.	Title Total	
Division :		unga-2 Length (km): 1.970 K."	4,	
	the Road: PW		o gargar	Litof.
	rogramme:	MAINTENANCE .	0 0	
Package :		Road Id No.:		
	the Project:	Ongoing/Completed/Under Maintenance	117	
Work is	a case of:	New Connectivity/Up gradation/ Maintenance ()	(4GSY)	
Sl. No.	根据是	Parameters to be checked	Remarks	i de d
1.	Pavement			
a)	Road Junction	S/U		
b)	Condition of S	S/U		
c)	Riding Quality	S/U		
d)	Road Camber	S/U		
e)	Whether free aggregates in o	Yes/No		
f)	Contraction Jo	Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2.	Cross Drainage			
a) 1	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U	
b) a	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	N/A-
3.	Road Furniture			0000
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance I			
a)	Status of ATR	's & any others	No	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Syed Sheegee Ahmel DESIGNATION: ABST. Engineer.