

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020 District: ~~Bansi~~ Mandhubani
 Division : Benipatti Length (km): 1.5 KM
 Name of the Road: Ultra High School to Sanyasi to
 Scheme Programme: MAINTENANCE ✓
 Package No.: N/A Road Id No.: 312100/2014
 Status of the Project: Ongoing Completed Under Maintenance ✓
 Work is a case of: New Connectivity Tip gradation Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SA
b)	Condition of Surfacing	SU
c)	Riding Quality	SA
d)	Road Camber	SO
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Madam Chaudhary
 29-12-2020
 (Signature)

NAME: Madam Chaudhary
 DESIGNATION: J. E.