

# FIELD INSPECTION REPORT

Date of Inspection: 31.12.2020	District: Samastipur	
Division: RWD Dalsinghsarai	Length(km): 1.01 Km.	
Name of Road: 704 to Nityadole.		
Scheme / Programme: MAINTENANCE	NGG (Gen)	
Package No:	Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/ Up gradation/ Maintenance		
Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	3
b)	Condition of Surfacing	3
c)	Riding Quality	3
d)	Road Camber	3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	3
f)	Constraction Joint provided or not(CC Pavement)	3
g)	Compaction of flank/slope & raincuts if any	3
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	1
c)	Condition of railings/slab/approach for Bridge	1
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	3
4	Compliance History	
a)	Status of ATRs & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	3
Unsatisfactory(U)	

NAME:

Asst. Engineer, Road.

Signature