

FIELD INSPECTION REPORT

Date of Inspection: 31.12.2020	District: Samastipur
Division: RWD Dalsinghgarai	Length(km): 3.327 Km
Name of Road : TOB to Gidaiola.	
Scheme / Programme: MAINTENANCE M.M.G. (Gen)	
Package No:	Road Id No:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up gradation/ Maintenance

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	S
f)	Constraction Joint provided or not(CC Pavement)	S
g)	Compaction of flank/slope & raincuts if any	S
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls , Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridge	S
3	Road Furniture	
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	S
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	S
Unsatisfactory(U)	

NAME:

DESIGNATION:

Heem Chandra Supt.
Asst. Engineer
M.O.R.S.

Signature
31/12/20