

FIELD INSPECTION REPORT

Date of Inspection :	9/12/20	District:	Gaya
Division :	Shershahat	Length (km):	0.789
Name of the Road:	Toi to Ghaheriya		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-122-811	Road Id No.:	L052
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U - S
a)	Road Junction condition	S/U -
b)	Condition of Surfacing	S/U -
c)	Riding Quality	S/U - S
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No -
f)	Contraction Joints provided or not (CC Pavement)	Yes/No -
g)	Compaction of flank/slope & raincuts if any	Yes/No - NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - SRI
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - Yes
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Not - Road requires needed shoulder and Patchwork

9/12/20
(Signature)

NAME: Chandra Lal Sumari

REDMI NOTE 6 PRO
MI DUAL CAMERA

J. E.