## FIELD INSPECTION REPORT

	+	7 1 LJ 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
Date of	inspection: 0 \	-01- 20	District: Roftag		
Division: RWD/Janny Systom-1			Length (km):		
MESSESSESSESSESSESSESSESSESSESSESSESSESS			Selax		
	Programme:	MAINTENANCE			
	No.: BR-2	BR-583	Road Id No.:		
	f the Project:	Ongoing/Completed	/Under Maintonance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance			
SI. No.		Parameters to	be checked	Remarks	
1.	Pavement				
a)	Road Junction	S/U			
b)	Condition of Surfacing			/S/U	
c)	Riding Quality			/S/U	
d)	Road Camber			√S/U	
c)	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2. )	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			/s/sri/U	
c)	Condition of railings/slab/approach for Bridges			/s/sri/U	
3.	Road Paraliure				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
4.	Compliance I	listory -			
a)	Status of ATR	's & any others			
31.3	Providence of the Park Control of the Park Con				

Overall Rating

Satisfactory (S)	"5"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

ModelSol.

(Signature)

NAME: Makesh Robals-l

DESIGNATION: 2'E.