FIELD INSPECTION REPORT

Date of Inspection: 31-12-20		District: Rollog.	
Division: RWDW) division, Sogaran-1		Length (km): 0. 740 K-B2	
Name of the Road: Te	Aug Josepho price	15% Road To Tenya Paguan	Tola.
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:			
SI. No.	Parameters to	be checked	Remarks

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	/S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	/ S/U
d)	Road Camber	/S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No.
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.1	Compliantes Elizabiy	
a)	Status of ATR's & any others	HO-

Overall Rating

Satisfactory (S)	"8"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Malast Postaded

DESIGNATION: JE