

FIELD INSPECTION REPORT

Date of Inspection: 21-12-2020		District: Purnea	
Division: Purnea		Length (Kms): 1.516	
Name of the Road: Faraya chara to Thana mulpan			
Scheme/Programme: Maintenance			
Package No:		Road ID No:	
Status of the Project: Ongoing/Completed/Under Maintenance		✓	
Work is a case of: New Connectivity/Up gradation/ Maintenance		✓	
Sl. No	Parameters to be Checked		Remarks
1.	Pavement		
a)	Road function condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓ S/SRI/U
c)	Condition of Railings/Slab/Approach for Bridges		✓ S/SRI/U
3.	Road Furniture		
a)	Whether sign boards Informatory/Cautionary Board km. & 200 m stones Pavement road markings are provided and maintained		Yes/No ✓
4.	Compliance History		
a)	Status of ATR's & any others		


Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	
Status :	

Name: Ranu Uday Kumar

Designation: J-C

RWD, Works Division, Purnea.


 21-12-2020
 (Signature)