

FIELD INSPECTION REPORT

Date of Inspection: 02.1.2021 District: KATI HAR
 Division: Bagraha Length (km): 0.260 Km
 Name of Road: Bagraha N 14/2007
 Scheme/Programme: MAINTENANCE
 Package No.: B.A. - 14/2 - 2007 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/Maintenance

Sl NO.	Parameters to be checked	Remarks
1	Payement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or no (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume Pipe culverts including its Pinting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sing boards/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and Maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any other	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	"U"

NAME: Bhagwesh Chandra Puj

DESIGNATION: Junior Engineer

(Signature)

02.1.2021

This road is highly damaged by flood in Sept. 2020.

(Signature)

02.1.2021