FIELD INSPECTION REPORT

Date of	Inspection: 09/01/2021 District: Kishangan J	
Division	: Kishandant-1 Length(km): 1.300	
Name o	the Road: Barbata Phriani Basti to tos.	
Scheme	Programme: GTSNY	
Package No.: Road Id No.:		
Status of the Project: Ongoing/Completed /Under Maintenance		
Work is	a case of: New Connectivity/ Up gradation / Maintenance	
S1. No	Parameters to be checked,	Remarks
1.	Pavement	V57U.
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates	Yes/No
	in case of CC Pavement.	
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No
g)	Compaction of flank / shop & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCG culverts	S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m	Yes/No
	stones/Pavement road markings are provided and maintained	
4.	Compliance History	-
a)	Status of ATR's & any others	

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

(Signature)

AE

NAME: Panjeet Kumur