

FIELD INSPECTION REPORT

Date of Inspection: 25.12.2020	District: Purnea	
Division: Purnea	Length (km): 1.640	
Name of the Road: Pipra Gunglas to Dargu Sino		
Scheme Programme: Maintenance		
Package No:	Road ID No:	
Status of the Project: Ongoing/Completed Under Maintenance ✓		
Work is a case of: New Connectivity/Up gradation/Maintenance ✓		
Sl. No	Parameters to be Checked	Remarks
1).	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Flank Slope & Raincuts if any	Yes/No ✓
2).	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of Railings/Slab Approach for Bridges	✓ S/SRI/U
3).	Road Furniture	
a)	Whether sign boards Informatory/Cautionary Board km & 200 m stones Pavement road markings are provided and maintained	Yes/No ✓
4).	Compliance History	
a)	Status of ATRs & any others	

Overall Rating :	Satisfactory (S)	
	Satisfactory but requires Improvement (SRI)	SRI
	Unsatisfactory (U)	
	Status :	

Name: Ranuclay Kumar
 Designation: J-C
 RWD, Works Division, Purnea,

25.12.2020
 (Signature)