FIELD INSPECTION REPORT

Date of Inspection:	30 12 2020	District: Same (alleger)	
Division: Se	mebur	Length (km): - 0-850	
Name of the Road:	gonna	elek To Hensen Tola	
Scheme/Programme;	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
The second secon			

L No.	Parameters to be checked	Remarks
1.	Pavement	Transpire.
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	SAU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
n	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	Alaca W
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRIA!
c)	Condition of railings/slab/approach for Bridges	
3,	Rend Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4	Compliance History	100
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SAL
Unsatiafactory (U)	

(Signature)

DESIGNATION: A-E