FIELD INSPECTION REPORT

ate of Inspection:	19.12.2020 D	Istrict: Nafandar.	
ivision: Bika	rslant. L	ength (km): 4.670 KM	('
ame of the Road:	NH-31 To Racho	ength (km): 4.670 Km	
cheme/Programme:	MAINTENAMER	VAISAIL	
ackage No.:		ond Id No.:	
tatus of the Project:	Ongoing/Completed/Un	gradation/ Maintenance	
Work is a case of:	Parameters to be	checked	Remarks
Sl. No.	Parameters to be	Circuit Circui	
1. Pavement			S/U
a) Road Junctio	Road Junction condition		S/U
b) Condition of	Condition of Surfacing		S/U
c) Riding Qual	Riding Quality		S/U
d) Road Cambo	Road Camber Whether free from defects such as visible cracks, exposed		Yes/No
e) aggregates i	aggregates in case of CC Pavement.		
f) Contraction	Contraction Joints provided or not (CC Pavement)		Yes/No
g) Compaction	of flank/slope & raincuts	if any	Yes/No
2. Cross Drai	nage		CICDIAL
	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b) Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
	Condition of railings/slab/approach for Bridges S		S/SRI/U
3. Road Furn	THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME		
a) Whether si	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4. Compliano	Compliance History		
a) Status of A	TR's & any others		1

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

* Road Damage due to flood - 2019 D. P.R. Submmited.

#sins/ 19:12:20 Signature)

NAME: A jeet Kumar Sinst

DESIGNATION: 7-2