


FIELD INSPECTION REPORT

Date of Inspection : 01-01-2021 District: Rorbas
 Division : RU D(W) Division Sasarni Length (km): 1.000 km
 Name of the Road: Gata Chau beg Nafar To Medhpur Bahadur/24
 Scheme/Programme: MAINTENANCE MHP (4515) Maintenance
 Package No.: 1 Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance
 Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	— S/U
b)	Condition of Surfacing	— S/U
c)	Riding Quality	— S/U
d)	Road Camber	— S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	— Yes/No
f)	Contraction Joints provided or not (CC Pavement)	— Yes/No
g)	Compaction of flank/slope & raincuts if any	— Yes/No
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	— S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	— S/SRI/U
c)	Condition of railings/slab/approach for Bridges	— S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	— Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


 01-01-21
 (Signature)

NAME: Mahesh Prasad Sah

DESIGNATION: J.E.