

FIELD INSPECTION REPORT

Date of Inspection : 29-12-2020 District: Madhyubani
 Division : Benipatti Length (km): 1.647 KM
 Name of the Road: Navtoli to pansalwa Dalit to/
 Scheme/Programme: MAINTENANCE
 Package No.: N/A Road Id No.: 31910000321
 Status of the Project: Ongoing/Completed/Under Maintenance ✓
 Work is a case of: New Connectivity/Up gradation/ Maintenance ✓

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank/slope & raincuts if any Not maintain	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U H/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U H/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	H/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Madan Choudhary
 29-12-2020
 (Signature)

NAME: Madan Choudhary

DESIGNATION: J.E.