

FIELD INSPECTION REPORT

Date of inspection: 30/12/2020 District: East Champaran
 Location: Chakia Length (Km): 1.70

Name of the Road: Amar Kishor Singh House to Narak Ram House.

Page No.: Road ID No.:

Status of the Project: Ongoing/Completed/Under Maintenance

It is a case of: New Connectivity/Up Gradation/Maintenance

Parameters to be checked	Remark
Pavement	
Road Junction condition	SR
Condition of Surfacing	S
Riding Quality	S
Road Camber	✓
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
Contraction Joints provided or not (CC Pavement)	NO
Compaction of Bank/slope & raincuts if any	—
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	SR
Condition of Abutment & Wing walls, Slab in RCC Culverts	—
Condition of railings/slab/approach for Bridges	—
Road Furniture	
Whether sign board/Informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SR
Compliance History	
Status of ATR's & any others	

Overall Rating : Satisfactory (S) Satisfactory but requires improvement (SR) Unsatisfactory (U)

NAME :

DESIGNATION :

30/12/2020
 A E
 Chakia

(Signature)