

FIELD INSPECTION REPORT

Date of Inspection : 9/12/20	District: Gajra-
Division : Shergahat	Length (km): - 0.60km
Name of the Road: L039 to Karmtar	
Scheme/Programme: MAINTENANCE	
Package No.:	Road Id No.:
Status of the Project: Ongoing Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U - S
a)	Road Junction condition	S/U - S
b)	Condition of Surfacing	S/U -
c)	Riding Quality	S/U - S
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No - NO
f)	Contraction Joints provided or not (CC Pavement)	Yes/No - Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No - NO
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U - S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U -
c)	Condition of railings/slab/approach for Bridges	S/SRI/U -
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No - NO.
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

SRI

Sign Board is not at site at present.
Sign Board is installed at site is necessary.

(Signature)