

FIELD INSPECTION REPORT

Date of Inspection: 03/01/2021 District: Kishangan
 Division: Kishangan - 1 Length(km): 1.350
 Name of the Road: Nagarpur to Lohb
 Scheme/Programme: GISAY
 Package No.: Road Id No.:

Status of the Project: Ongoing/Completed /Under Maintenance


Work is a case of: New Connectivity/ Up gradation / Maintenance

S1. No	Parameters to be checked	Remarks
1.	Pavement	✓ S/U
a)	Road Junction Condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints Provided or not (CC Pavement)	Yes/No ✓
g)	Compaction of flank / shop & raincuts if any	Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its Painting	S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	NA S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	-
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory(U)	-

NAME: Ranjeet Kumar


 (Signature)
 AE