## FIELD INSPECTION REPORT

Date of Inspection: 18/12/20 District: ondsv2			
Name of Road: Sosi (Hulter-21) Mais 218 24 (2) 1278 210			
		MAINTENANCE MMNSY (SS)	
Package No. Road ID No.			
Status of the Project:		Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
Sl.No		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition S/U		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Š/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any  Yes/No		
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting  S/SRI/U		
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U
a)	Road Furniture  Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4			
a)	Status of ATR & any	others	NA
Overall Grading: Satisfactory (S)			
		Satisfactory but requires Improvement(SRI)	SRI
		Unsatisfactory (U)  2017 of un Martin BT 311B15  2018 of 21 3029M1 on 1012fel Or  What Rown (Signature)	28/12/2
Name: 1 Degisnat	ion Turns	or Engineer (signature)	