

FIELD INSPECTION REPORT

Date of Inspection: 30/12/2020

District: East Champaran

Vision: Chakia

Length (Km):

Name of the Road: Lohwar, Mukhi to Link Road LO 37

Package No.:

Road ID No.:

Status of the Project:

Ongoing/Completed/Under Maintenance

Work is a case of:

New Connectivity/Up Gradation/ Maintenance

No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	SR)
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	yes
g)	Compaction of Bank slope & raincuts if any	—
2.	Gross Drainage	—
a)	Condition of head walls in Hume pipe culverts including its painting	SR)
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	SR)
b)	Compliance History	
c)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

Satisfactory but requires improvement (SR)

Unsatisfactory (U)

SR)

NAME :

DESIGNATION :

[Signature]
30/12/2020
A.E.
Chakia

(Signature)