

FIELD INSPECTION REPORT

Date: 29-12-2020	District: East Champaran
Location: Rakia	Length (Km): 0.700 Km
Road Name: Jadu paswan Laukote to PWD Road near Ramkishan Paswan	
Road ID No.:	
Project:	Ongoing/Completed/Under Maintenance
New Connectivity/Up Gradation/ Maintenance	
Items to be checked	Remarks
1. Pavement condition	S
2. Condition of Surfacing	S
3. Quality	S
4. Number	S
5. Free from defects such as visible cracks, exposed aggregates in CC Pavement.	yes/no
6. Expansion Joints provided or not (CC Pavement)	yes
7. Condition of Bank/slope & raincuts if any	—
8. Condition of head walls in Hume pipe culverts including its painting	SRI
9. Condition of Abutment & Wing walls, Slab in RCC Culverts	—
10. Condition of railings/slab/approach for Bridges	—
11. Structure	SRI
12. Sign board/Informatory/cautionary Board/Km & 200m	S
13. Movement road markings are provided and maintained	
14. Accidents History	
15. ATR's & any others	
Overall Rating:	Satisfactory (S)
	Satisfactory but requires improvement (SRI)
	Unsatisfactory (U)

Note:— some portion p.c.c road damaged due to flood. Flood.

[Signature]
29/12/2020
A-E
Chakra

(Signature)

ION: