

FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020		District: Purnea	
Division: Purnea		Length (km): 1.200	
Name of the Road: Bank: Chakbigha Nudia to Lohar			
Scheme Programme: Maintenance			
Package No:		Road ID No:	
Status of the Project: Ongoing/Completed/Under Maintenance ✓			
Work is a case of: New Connectivity/Up gradation/Maintenance ✓			
Sl. No	Parameters to be Checked	Remarks	
1.	Pavement	✓ S/U	
a)	Road Junction condition	✓ S/U	
b)	Condition of Surfacing	✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of Bank/Slope & Ramps if any	✓ Yes/No	
2.	Cross Drainage		
a)	Condition of Head walls in Home Pipe Culverts including its painting	✓ S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in R/C culverts	S/SRI/U N/A	
c)	Condition of Railings/Slab Approach for Bridges	S/SRI/U N/A	
3.	Road Furniture		
a)	Whether sign boards/Informatory/Cautionsary Board 2m & 200 m stones/Pavement road markings are provided and maintained	✓ Yes/No	
4.	Compliance History		
a)	Status of AIR's & any others		

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
	Status :	

Name: Ranu Kumar
 Designation: J.C.
 RWD, Works Division, Purnea.

21.12.2020
 (Signature)