

FIELD INSPECTION REPORT

Date of Inspection: 22.12.2020		District: Purnea	
Division: Purnea		Length (km): 1.150	
Name of the Road: Darga area to Belur - 1000 clauless to 19			
Scheme Programme: Maintenance		Road ID No:	
Package No:		Status of the Project: Ongoing/Completed/Under Maintenance ✓	
Work is a case of:		New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked		Remarks
1.	Pavement		✓ S/U
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of Flank/Slope & Raincuts if any		✓ Yes/No
2.	Cross Drainage		✓ S/SRI/U
a)	Condition of Head walls in Hume Pipe Culverts including its painting		S/SRI/U 7.0
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.		S/SRI/U 11.4
c)	Condition of Railings/Slab/Approach for Bridges		
3.	Road Furniture		✓ Yes/No
a)	Whether sign boards/Informatory/Cautionary Board km & 200 m stones Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :	Satisfactory (S)	5
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
	Status :	

Name: Ranuwar Kumar
 Designation: S.E.
 RWD, Works Division, Purnea.

20/12/2020
 (Signature)