FIELD INSPECTION REPORT

ate of I	nspection: 231	12/10 District: 972812	
Name of	Road:	MMNEX SEXIZADEMI SHEMINGO	Marster
Scheme/	Programme:	MAINTENANCE VITSHY	
Package	No.	Road ID No.	
Status o	of the Project:	Onging/Completed/Under Maintenance	
Work is a case of:		New Connectivity/ Up Gradation/ Maintenance	
SLNo		Parameters to be Checked	Remarks
1	Pavement		
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slpoe & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of headwalls inn Humepipe culverts including its painting		S/SRI/U M
b)	Condition of Abutment & Wings walls, Slab in RCC culverts		S/SRI/U H
c)	Condition of railings/slabs//approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.		Yes/No
4	Compliance History		
a)	Status of ATR & any others		MA
Overall	Grading:	Satisfactory (S)	
Overall Grading:		Satisfactory but requires Improvement(SRI)	192
		Unsatisfactory (U)	

Name: Romcharba Rom Degisnation Turnion Engèner (Signature) (141)