

FIELD INSPECTION REPORT

Date of inspection : 23.12.2020		District : Purnea
Division : Purnea		Length (km) : 0.45
Name of the Road : Ghusman Jala to Khat		
Scheme/Programme :	Maintenance	
Package No.	Road ID No.	
Status of the Project :	Ongoing/Completed/Under Maintenance ✓	
Work is a case of	New Connectivity/Up gradation/Maintenance ✓	
Sl. No	Parameters to be Checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of Flank Slope & Raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of Head walls in Hume Pipe Culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts.	S/SRI/U
c)	Condition of Railings-Slab Approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/Informatory/Cautionary Board km & 200 m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating :	Satisfactory (S)	S
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	
	Status :	

Name : Ram uday Kumar
 Designation : J-1
 RWD, Works Division, Purnea.

23.12.2020
 (Signature)