

FIELD INSPECTION REPORT

Date of Inspection :	29/12/2020	District :	Alwar
Division :	Area	Length (km) :	1.926 km
Name of the Road :	Area Bakhara Road to Dubey chakra		
Scheme/Programme :	MAINTENANCE	Road Id No. :	
Package No. :			
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/N/A
b)	Condition of Surfacing	✓/N/A
c)	Riding Quality	✓/N/A
d)	Road Camber	✓/N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Home pipe culverts including its painting	S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U
c)	Condition of railings/slab/approach for Bridges	S/SR/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SR
Unsatisfactory (U)	

[Signature]
29/12/2020
(Signature)

NAME: