

FIELD INSPECTION REPORT

Date of Inspection: 28/12/20		District: 472812
Name of Road:	715-मिर्जापुर-सिद्धार्थन 24 पुरादपुर	
Scheme/ Programme:	MAINTENANCE M M WSY (SC)	
Package No.	Road ID No.	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance	
SLNo	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	
a)	Condition of headwalls in Humepipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	Yes/No
4	Compliance History	
a)	Status of ATR & any others	NA

Overall Grading:

Satisfactory (S)	-S-
Satisfactory but requires Improvement(SRI)	
Unsatisfactory (U)	

Name: Ramchandra Ram
 Designation: Junior Engineer

(Signature) 