FIELD INSPECTION REPORT

		01-01-24	District: Rokt-8	
Date of I			Length (km): 8.750	
Division	: RwD[w) divi	sion, Sasaron 1	twa	
	The second secon	MAINTENANCE	2 work completed	-
	Programme:	MAINTENANCE	Road Id No.:	
Package		Denoing/Complete	d/Under Maintenance	
	f the Project:	New Connectivity	Up gradation/ Maintenance	
Work is a case of:		Parameters to be checked		Remarks
1.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of S	- S/U		
c)	Riding Quality			~S/U
d)	Road Camber			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
-	Gross Drains	ge		
a)	Condition of l	/s/srl/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			- S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
.: 3.	Road Furnite	ire		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.1	Compliantes.	:Tiskisky		3.4.2
8)	Status of ATR	l's & any others		

Overall Rating

Satisfactory (S)	``S ``
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

MoodadSal

(Signature)

NAME: Makesh Pooded Sol

DESIGNATION: