

FIELD INSPECTION REPORT

Date of Inspection: 21.12.2020	District: Samastipur
Division: RWD Dalabighat	Length(km):
Name of Road: 1070 to Potha Kola, Sadar Tola.	
Scheme / Programme: MAINTENANCE	Package No: 44554
Status of the Project: Ongoing/Completed/Under Maintenance	Road Id No:
Work is a case of: New Connectivity/ Up gradation/ Maintenance	

Sl. No	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction Condition	3
b)	Condition of Surfacing	3
c)	Riding Quality	3
d)	Road Camber	3
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	3
f)	Construction Joint provided or not(CC Pavement)	3
2	Cross Drainage	2
a)	Condition of head walls in Hume pipe culverts including its painting	1
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	1
c)	Condition of railings/slab/approach for Bridge	1
3	Road Furniture	1
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	3
4	Compliance History	
a)	Status of ATRs & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement(SRI)	
Unsatisfactory(U)	

NAME: *Breen Charles Suptg.*
 DESIGNATION: *Asst. Engineer*
M.D.

Signature
 21/12/20