

# FIELD INSPECTION REPORT

|                        |                                             |              |             |
|------------------------|---------------------------------------------|--------------|-------------|
| Date of Inspection :   | 29-12-2020                                  | District:    | Madhubani   |
| Division :             | Benipatti                                   | Length (km): | 0.963 km    |
| Name of the Road:      | Toi to Utra                                 |              |             |
| Scheme Programme:      | MAINTENANCE ✓                               |              |             |
| Package No.:           | BR-212-192                                  | Road Id No.: | 31910002076 |
| Status of the Project: | Ongoing Completed Under Maintenance ✓       |              |             |
| Work is a case of:     | New Connectivity Up gradation Maintenance ✓ |              |             |

| Sl. No. | Parameters to be checked                                                                                             | Remarks     |
|---------|----------------------------------------------------------------------------------------------------------------------|-------------|
| 1.      | <b>Pavement</b>                                                                                                      |             |
| a)      | Road Junction condition                                                                                              | ✓           |
| b)      | Condition of Surfacing                                                                                               | ✓           |
| c)      | Riding Quality                                                                                                       | ✓           |
| d)      | Road Camber                                                                                                          | ✓           |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No ✓    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No ✓    |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No ✓    |
| 2.      | <b>Cross Drainage</b>                                                                                                |             |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U N/A |
| b)      | Condition of Abutment & Wing walls. Slab in RCC culverts                                                             | S/SRI/U N/A |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U N/A |
| 3.      | <b>Road Furniture</b>                                                                                                |             |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No ✓    |
| 4.      | <b>Compliance History</b>                                                                                            |             |
| a)      | Status of ATR's & any others                                                                                         | N/A         |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            |     |
| Satisfactory but requires Improvement (SRI) | SRI |
| Unsatisfactory (U)                          |     |

*Madan*  
29-12-2020  
(Signature)

NAME: Madan chandhan

DESIGNATION: J.E.

*29/12/2020*  
*HE*