FIELD INSPECTION REPORT

		. 2 111		
		1-01-84-	District: Rolley	
Date of I	nspection: 0	1 411	Length (km): o SSOK V	
Division	: entrelling	Lawrosdra I		
Name of	the Road:	chawalfy four	s Sahwaliya Kala.	
Scheme/	Programme:	MAINTENANCE		
Dealess No.		1.100.57	Road Id No.:	
		Ongoing/Completed/Under Maintenance		
Status of the Project:		Ongoing/Completes	1 1 si - 134 si stamonos	
Work is a case of:			Jp gradation/ Maintenance	T
SI. No.	Parameters to be checked		Remarks	
1.	Pavement			-
a)	Road Junction condition			- S/U
/				1/001

SI. No.	Parameters to be checked	Remarks		
1.	Pavement			
a)	Road Junction condition	- S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	<u> </u>		
d)	Road Camber	/ S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No		
g)	Compaction of flank/slope & raincuts if any	Yes/No		
1.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-3/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.4	Compiliaties History	19		
a)	Status of ATR's & any others			

Overall Rating

Satisfactory (S)	18"
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

MosaddSol

(Signature)

NAME: Makest Porded Sol

DESIGNATION: 3 B