FIELD INSPECTION REPORT

Data of I	nspection: 0)	- 0 - 21. District:	Rokdos	
Division	· ow plw) divi	sion, Sasaromi Length (km	1): 0.550 K-BL	
Name of	the Road: Kar	mas Hole to Kasmas	: V	not stor
the state of the s	Programme:	MAINTENANCE		2021 746K
Package		Road Id No		
	the Project:	Ongoing/Completed/Under Main	lenance	
	a case of:	New Connectivity/Up gradation/	Maintenance	
SI. No.	Parameters to be checked			Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
<u>d)</u>	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Gross Drains			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U	
c)	Condition of railings/slab/approach for Bridges		S/SRI/U	
. a.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			
4.1	Compliants.	ileofy -		1
8)	Status of ATH	's & any others		

Overall Rating

Satisfactory (S)	"8"
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

Marsadel

(Signature)

NAME: Makest Porgaded

DESIGNATION: 32