17.18.9.5X

## FIELD INSPECTION REPORT

Date of Inspection: 01-01-27  Division: Rub(w) division, Subarom 1		District: Rollar	
		Length (km): 0.550	
Name of the Road: Bi		To Panaili	
Scheme/Programme:	MAINTENANCE week not st		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

SI. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance Flatory	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	``S `
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Modedsol.

(Signature)

NAME: Makest Possed Sol

DESIGNATION: JE