FIELD INSPECTION REPORT

	District: Rokyes		
Date of I	nspection: 01-01-20		
Division	: Rudwalnyon, social I	gaun	
Name of	M. 131 C. C. H.		
Genetite	Road Id No.: -		
Package	1 Index Maintenance		
	the Project: Ongoing/Completed/Order Maintenance a case of: New Connectivity/Up gradation/ Maintenance		
SI. No.	Parameters to be checked	Remarks	
1.	Pavement	/	
a)	Road Junction condition	S/U '	
b)	Condition of Surfacing	VS/U	
c)	Riding Quality	SIU	
d)	Road Camber	SIU	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	_Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	- Yes/No	
g)	Compaction of flank/slope & raincuts if any	Nes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	√\$/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
. a.	Road Purniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History	AP.	
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)	'S '
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

1000000lsd

(Signature)

NAME: Mohest Bosad Sol

DESIGNATION: JE