12.1810.03

FIELD INSPECTION REPORT

Date of Inspection :	1-01-21 District: Robbas	
	l ength (kmi): 0.400	
Division: Reserve	Has Indeptus by Decord to liber Krown Hass	izan Tola
Scheme/Programme:	MAINTENANCE M. M. S. S. J.	
Package No.:	Road Id No.:	rook not stop
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
SI. No.	Parameters to be checked	Remarks
1. Pavement		
a) Road Junction condition		S/U
b) Condition of	b) Condition of Surfacing	
c) Riding Quali	Riding Quality	
d) Road Cambo	Road Camber	
	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f) Contraction	Contraction Joints provided or not (CC Pavement)	
g) Compaction	Compaction of flank/slope & raincuts if any	
2. Gross Drain	130	
THE PART OF THE PA		
b) Condition of	Condition of Abutment & Wing walls, Slab in RCC culverts	
c) Condition of	Condition of railings/slab/approach for Bridges	
3. Road Furnit	ire .	21.
41	n boards/informatory/cautionary Board/km & 2 ent road markings are provided and maintained	200m Yes/No
A. Compliance	EIBOW -	,,,
a) Status of ATI	l's & any others	

Overall Rating

Satisfactory (S)	's '
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Mosadadsal

(Signature)

NAME: Makesh Porssed Sol

DESIGNATION: JR