FIELD INSPECTION REPORT

		1-01-21	District: Rootes	
Date of t	malice creases .	The second secon	Length (km): 0.600	
		sim, Sasaron -1	has to Josiphy Makadet	10/4
		da Chaubey Ho MAINTENANCE		
V	Programme:		Road Id No .: - work	Grote tent
Package		2) Casy	/Under Maintenance	
	the Project:	New Connectivity/L	Jp gradation/ Maintenance	
Work is	a case of:		·	Remarks
SI. No.	Parameters to be checked			Kemaria
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed yes/haggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
. g)	Compaction of flank/slope & raincuts if any			Yes/No
4.1	Gross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			s/sri/u
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
a.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
	Compilance P	listory.		
8)	Status of ATR	's & any others		

Overall Rating

Satisfactory (S)	'3'
Satisfactory but requires improvement (SRI)	
Unsatisfactory (U)	

ModadSol.

(Signature)

NAME: Makesh Prosadsok

DESIGNATION: 3 2